

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Juliana Kang
Toshihiko Ouchi)	
	:	Group Art Unit: 2874
Appl. No.: 10/735,903)	
	:	Confirmation No.: 3907
Filed: December 16, 2003)	
	:	
For: OPTICAL WAVEGUIDE DEVICE,)	
OPTICAL AND ELECTRICAL ELEMENTS	:	
COMBINED DEVICE, METHOD OF DRIVING)	
THE SAME, AND ELECTRONIC EQUIPMENT	:	
USING THE SAME)	
	:	
U.S. Patent No.: 7,151,865 B2)	
	:	
Issued: December 19, 2006)	April 10, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to an error which appear in the printed patent as a result of a Patent and Trademark Office mistake, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Donald H. Heckenberg, Jr./

Donald H. Heckenberg, Jr.
Attorney for Patentee
Registration No. 60,081

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

JJO:kag

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,151,865 B2

DATED : December 19, 2006

INVENTOR(S) : Toshihiko Ouchi

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 19, "cross sectional" should read --cross-sectional--.

Line 52, "cross sectional" should read --cross-sectional--.

COLUMN 4:

Line 9, "a optical" should read --an optical--.

Line 18, "a optical" should read --an optical--.

COLUMN 6:

Line 37, "an transmission" should read --a transmission--.

COLUMN 7:

Line 32, "overlie" should read --overlay--.

Line 51, "through via" should read --via--.

Line 62, "cross sectional" should read --cross-sectional--.

COLUMN 8:

Line 4, "though a via" should read --via--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,151,865 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTERS TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,151,865 B2
DATED : December 19, 2006
INVENTOR(S) : Toshihiko Ouchi

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 19, "This" should read --The--.

Line 49, "Po;" should read --Po,--.

COLUMN 14:

Line 2, "a" should read --an--.

Line 50, "chip size" should read --chip-size--.

COLUMN 16:

Line 20, "chip" should read --chips--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,151,865 B2

No. of add'l. copies
@ 30¢ per page

